



Special Notice

URGENT

Date: 23 August 2021
Subject: Incorrect Altitude on Instrument Approach Procedures
Cycle 2108

The following procedures were delivered with an incorrect altitude.

| Airport | Procedure | Error |
|---------|---------------------------------|---|
| KMSS | RNAV (GPS) RWY 23 (R23) | The minimum altitude at SALAS waypoint should be at or above 2500' on the final approach. |
| KCMH | RNAV (RNP) Z RWY 28L (H28LZ) | The minimum altitude at WILSO waypoint should be at or above 4800' on the JESCE transition. |
| KHWQ | RNAV (GPS) RWY 27 (R27) | The minimum altitude at ZERZO waypoint should be at or above 9600' on the missed approach. |

AeroNavData advises to use the procedures with extreme caution until an updated data delivery is made. The data will be updated to reflect the latest source in the cycle 2109 data effective Thursday, September 9, 2021.

Special notices are disseminated to notify customers of issues with navigational data which may affect flight operations or safety. Information contained herein should be immediately relayed to appropriate personnel!

Important: Check NOTAMs and other pertinent information prior to flight.

All questions regarding this Special Notice should be addressed to:
Email: production@aeronavdata.com

9735 Landmark Pkwy,
Suite 200, St. Louis MO 63127

CC#
Form CC# 2211001015